



TECHNICAL BULLETIN

BULLETIN #: 000001
DATE: 6/18/07
RE: FORD SUPER DUTY PITMAN ARM
PART #: FD700

Consumers;

It has come to our attention that Pitman Arm part number FD700 used in Pro Comp Suspension systems for 2005-2008 Ford Super Duty trucks may have a label attached that has an incorrect installation torque specification. The correct final torque setting as called out in the kit installation instruction booklet is 350 Foot Pounds. Improper installation procedure and/or failure of setting final torque to 350 Foot Pounds could result in damage to the Pitman Arm itself or to other vehicle steering components.

It is important that you inspect the Pitman Arm. If you suspect a Pitman Arm that may not have been installed as called out in the installation instruction booklet, please contact our Customer Service Tech Department at (800)-776-0767 or (619)-216-1444. They will be able to assist you with any questions you may have in regards to the pitman arm installation.

Warehouse Distributors and Dealers;

Please contact us at the telephone numbers as listed above in the case you have inventory of FD700's to enable us to supply correct labeling.

Thank you for your cooperation.

John Corrao
VP Mfg and Eng
Pro Comp Suspension

PRO COMP SUSPENSION

2360 BOSWELL ROAD
CHULA VISTA, CA. 91914

TOLL FREE: (800)-776-0767 PHONE: (619)-216-1444 FAX: (619)-216-1474

WWW.EXPLORERPROCOMP.COM